

# ALL WELDING STUDENTS REQUIRED EQUIPMENT

**EACH WELDING STUDENT WILL BE REQUIRED TO FURNISH THE  
FOLLOWING PERSONAL EQUIPMENT:**

1. Safety glasses (Clear Lens)
2. Burning Goggles
3. Welding Cap
4. Welding Hood with # 10 Filter Lens and Clear Lens
5. Long Sleeved Welding Shirt 100% Cotton
6. Welding Gloves
7. Striker
8. Chipping Hammer & Wire Brush
9. Channel Lock Pliers

*Each welding student is required to wear leather boots.*

*No tennis shoes or sandals will be permitted.*

For your safety, no butane cigarette lighters will be allowed in the shop area.  
Member suppliers will be offering educational discounts to ABC Students.