



ALL Welding Students **Required Equipment**

Each welding student will be required to furnish the following personal equipment:

1. Safety glasses (Clear Lens)
2. Burning Goggles
3. Welding Cap
4. Welding Hood with # 10 Filter Lens and Clear Lens
5. Hard Hat Bracket for Welding Hood **Fall 2021**
6. Long Sleeved Welding Shirt - 100% Cotton
7. Welding Gloves
8. Steel toe leather boots – NO TENNIS SHOES OR SANDALS
9. Face Shield
10. Striker
11. Chipping Hammer & Wire Brush
12. Channel Lock Pliers
13. 4-inch Grinder w/paddle switch, handle, guard, grinding wheels & wire wheels
14. #2 cable 10' 200 AMP Electrode Holder with male quick connect **Fall 2021**

LEVEL 3 STUDENTS ONLY:

15. 1/8" x 7" 2% Thoriated Tungsten Electrode Ground (10 pack) **Fall 2021**
16. 150 AMP 12' Long Tig Rig **Fall 2021**

**SAFETY GLASSES MUST BE WORN AT ALL
TIMES IN THE SHOP AREA!**

For your safety NO BUTANE CIGARETTE LIGHTERS will be allowed in the shop area.

Member suppliers will be offering educational discounts to ABC Students.

NO SMOKING ON CAMPUS & NO BREAKS!